A Three-Quarter Bath in Half the Space

A small bath makes the most of its 25-sq.-ft. footprint

Craftsman-style house in Northfield, Minn. The house was built in 1911 by a Swedish carpenter who occupied it for the next 50 years. Afterward, the house endured a long line of owners who neglected it over several decades. The Wilmots bought the house at a garage sale. (The owner had included the house in the list of items for sale in her newspaper ad.) It needed work, but it was a solid structure with plenty of character that had lots of potential.

While remodeling the upstairs bathroom was at the top of their priority list, the Wilmots also wanted a more complete bath to replace the quasi-powder room that occupied a closet in the first-floor bedroom. (The closet, approximately 3 ft. by 8 ft., contained a toilet but no sink.) After studying the space and making preliminary drawings, Wilmot realized that the space was just big enough for a sink, a shower stall, and a relocated toilet.




Problem: It's not just small—it's claustrophobic

Solution: Rather than install a new exterior window, Wilmot opted for a cabinet above the toilet to store towels, toilet paper, and medicine-cabinet items. To provide natural light and to reduce the tight feel of the room, he replaced the wood panels in the door with translucent glass that gives the added benefit of showing when the room is occupied.

Architect: Steve Wilmot, SMSQ Architects, Northfield, Minn. **Contractor:** Duden & Viken Builders, Northfield, Minn.







According to code, at least 50% of any room with a sloped ceiling must be at or above the minimum height of 84 in., and no portion may be below 5 ft. Code also specifies a minimum ceiling height of 80 in. over fixtures. The ceiling height below the stairs was just high enough to satisfy code with the minimum height at the front of the toilet.





Problem: A vertically challenged location

Solution: The intended bathroom space—a closet—was under the stairs, so in addition to being small and narrow, it had height restrictions. At one end beneath the stair stringers, there was just enough headroom to stand. That determined the toilet's location. The opposite end of the space was a better fit for the shower stall.

"aha!" moment

Access on the long side of a rectangular room is generally easier, all the more so in a tiny room. Wilmot realized that the existing door's location wouldn't work, and he considered opening the wall below the first stair landing so that the entrance would be from the kitchen. However, that arrangement would provide only enough space for a half-bath. Instead, he moved the door to the middle of the bedroom side, which left enough room for both a toilet and a shower stall. The one downside: Wilmot had to choose a small sink to create enough clearance at the doorway.







Notable elements

Light fixture: Rejuvenation **Tile:** Subway Ceramics

Dual-flush toilet: Sterling Plumbing **Antique sink:** Garage sale